
F16, 1



F16.2


20


Compress quantity of MgBz powder Lzz

Sinter the quantity
of Mg Bz powder while
being compressed

Cool the sintered body

26





F16.5

Provide sold pellet of MgBz

62 J

Direct beam of pulsed laser onto the pellet to eject particles of MgBz

C4 J

Deposit MgBz particles ejected by the beam of the laser on a substrate

66

